



FIRE RESISTANT TIMBER DOOR SCHEME

Certificate number: IFCC 1272

This is a product certificate to certify that

Nolan Products Ltd

Station Road,
Newcastle West,
Co. Limerick V42 TW83

Tel: +353 69 61390

who fabricate the following timber fire doors:

Halspan FD30, FD60
Strebord FD30, FD60 & Vicaima FD30
Warm Springs FD60

have satisfied the requirements of the SDP01 Fire resistant Timber Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 60 minutes integrity** are detailed on page 2 of this certificate.



First Issued: 03 November 2016
Re-issued 26 June 2019
Valid to: 02 November 2022
Issue No: 3



175

A handwritten signature in black ink, which appears to read 'Ian Woodhouse', is written over a light blue horizontal line.

Ian Woodhouse
Director of Certification

IFC Certification Ltd
20 Park Street, Princes Risborough, Buckinghamshire, England HP27 9AH
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

F27 ©IFC Certification Ltd 2004

Certificate number: IFCC 1272

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/ Test Report
Halspan Prima	FD30	HS01 IFCA/06166
Halspan Prima	FD60	HS02 IFCA/06167
Halspan Optima	FD30	HS03 PAR/10341/01
Halspan Optima	FD60	HS04 PAR/10341/02
Strebord 44	FD30	Chilt/A02066
Strebord 54	FD60	Chilt/A02067
Vicaima	FD30	FEA/99122A
Warm Springs	FD60	Chilt/A12138

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.