



## FIRE RESISTANT TIMBER DOOR SCHEME

***Certificate number: IFCC 1414***

This is a product certificate to certify that

### ***Woodmarque Architectural Joinery***

16 Mullaghbane Rd.,  
Dungannon, Co. Tyrone  
BT70 1SR  
UK  
Tel: 02887724907

who fabricate the following timber fire doors:

**Halspan FD30, FD60, FD90 & FD120**  
**Strebord FD30, FD60, FD90 & FD120**  
**Egger FD30**  
**Moralt FD30 & FD60, Vicaima FD30 & FD60**

have satisfied the requirements of the SDP01 Fire Resistant Timber Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed on page 2 of this certificate.



Initial certification: 10 October 2018  
Revised 08 January 2021  
Valid to: 08 October 2023  
Issue status: 2

Ian Woodhouse  
Director of Certification



175

IFC Certification Ltd  
20 Park Street, Princes Risborough, Buckinghamshire. England HP27 9AH  
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: [info@ifccertification.com](mailto:info@ifccertification.com) Web: [www.ifccertification.com](http://www.ifccertification.com)  
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

F27 ©IFC Certification Ltd 2004

## ***Certificate number: IFCC 1414***

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

<b>Doorset Description</b>	<b>Fire Rating</b>	<b>Assessment/ Test Report</b>
Halspan Optima	FD30	Chilt/A01204
Halspan Optima	FD60	Chilt/A01205
Halspan Prima	FD30	FEA/F97174
Halspan Prima	FD60	FEA/F96103
Halspan	FD90	Chilt/A05151
Halspan	FD120	BMT/CAN/F15082
Strebord 44	FD30	Chilt/A02066
Strebord 54	FD60	Chilt/A02067
Stredor 44	FD30	BMT/CAN/F15159
Stredor 54	FD60	WF377027
WSCP	FD60, FD90 & FD120	Chilt/A12138
Egger Eurospan	FD30	Chilt/A13085
Moralt Laminesse Klassik & FireSmoke	FD30	CNA/F14274
Moralt Laminesse FireSmoke & FireSafe	FD30	PAR/12519/01
Moralt Laminesse FireSmoke & FireSafe	FD60	PAR/12519/02
Moralt Laminesse FireSound	FD30 & FD60	PAR/14559/01
Moralt Laminesse FireSound	FD30 & FD60	PAR/12519/03
Vicaima	FD30	FEA/F99112A
Vicaima	FD60	Chilt/A13093

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

**It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.**

**Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.**

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.