



FIRE RESISTANT TIMBER DOOR SCHEME

Certificate number: IFCC 1607

Certificate only valid if verified on website - www.ifccertification.com

This is a product certificate to certify that

JPC Door Sets Ltd

7 - 10 Advanced Business Park
Burdock Close
WS11 7FG

Tel: 01543 506699

Who fabricate the following timber fire doors and or doorsets:

**Strebord FD30, FD60, Vicaima FD30, FD60,
Tri-Sound FD30, FD60, Warmsprings FD60, FD90,
FD120, Halspan FD30, FD60, FD90, FD120,
Moralt FD30, FD60, FD90**

have satisfied the requirements of the SDP01 Fire Resistant Timber Door scheme. This includes the testing of products to **BS476: Part 22** the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed on page 2 of this certificate.



Initial certification: 15 October 2020

Reissued: 13 November 2020

Valid to: 14 October 2025

Issue status: 2

Ian Woodhouse

Director of Certification

Page 1 of 2



175

IFC Certification Ltd

20 Park Street, Princes Risborough, Buckinghamshire. England HP27 9AH

Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com

Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

Certificate number: IFCC 1607

The production of fire resistance timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/Test Report
Strebord	FD30	IFCA/08037
Strebord	FD60	IFCA/08038
Stredor 44	FD30	BMT/CAN/F15159
Stredor 54	FD60	WF 377027
Warmsprings	FD60, FD90, FD120	IFCA/07019
Trisound	FD30	PAR/12033/01
Trisound	FD60	PAR/13088/01
Vicaima	FD30	FEA/F99112A
Vicaima	FD60	Chilt/A13093
Halspan Prima	FD30	06166 (HS01)
Halspan Prima	FD60	06167 (HS02)
Halspan Optima	FD30	PAR/10341/01 (HS03)
Halspan Optima	FD60	PAR/10341/02 (HS04)
Halspan	FD90	PAR/10513/01 (HS05)
Halspan	FD120	PAR/10513/02 (HS06)
Halspan Prima Plus	FD30	IFCA/15953/01
Halspan Prima Plus	FD60	IFCA/15953/02
Moralt Laminesse FireSmoke & FireSafe	FD30	PAR/12519/01
Moralt Laminesse FireSmoke & FireSafe	FD60	PAR/12519/02
Moralt Laminesse FireSound	FD30, FD60	PAR/12519/03
Moralt Laminesse FireSound	FD30	PAR/14559/01
Moralt Outdoor FERRO FireSafe	FD30	PAR/13145/01
Moralt Outdoor FERRO FireSafe	FD60	PAR/18099/01

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version /revision of the above assessment/ test reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.