



FIRE RESISTANT TIMBER FIRE DOORS

Certificate number: IFCC 1150

Certificate only valid if verified on website - www.ifccertification.com

This is a product certificate to certify that

SAS International Limited

Apollo Park
Rounds Green Road
Oldbury, West Midlands
B69 2DA
Tel: 0121 511 1300

"Who manufacture door blanks used for the fabrication of the following fire doors & doorsets"

**Halspan FD30, FD60 Strebord FD30, FD60 Egger FD30
Moralt FD30, FD60 Vicaima FD30, FD60
Own Design FD30, FD60**

have satisfied the requirements of the SDP01 Fire resistant Timber Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 60 minutes integrity** are detailed on page 2 of this certificate.



First Issued: 10 July 2015
Reissued: 15 July 2020
Revised 17 September 2021
Valid to: 9 July 2025
Issue No:5



175

A handwritten signature in black ink, appearing to read 'Ian Woodhouse'.

Ian Woodhouse
Director of Certification

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire. UK, HP27 9AH
Tel: +44 (0)1844 275500 Fax: +44 (0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

Certificate number: IFCC 1150

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Description	Fire Rating	Assessment/ Test Report
Halspan Prima	FD30	06166 (HS01)
Halspan Prima	FD60	06167 (HS02)
Halspan Optima	FD30	PAR/10341/01 (HS03)
Halspan Optima	FD60	PAR/10341/02 (HS04)
Strebord 44	FD30	Chilt/A02066
Strebord 54	FD60	Chilt/A02067
Stredor 44	FD30	BMT/CAN/F15159
Stredor 54	FD60	WF377027
Egger Eurospan	FD30	Chilt/A13085
Vicaima	FD30	FEA/F99112A
Vicaima	FD60	Chilt/A13093
SAS	FD30	PAR/16481/01
SAS	FD60	PAR/9882

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.