



FIRE RESISTANT TIMBER FIRE DOORS

Certificate number: IFCC1629

Certificate only valid if verified on website www.ifccertification.com

This is a product certificate to certify that

Esprit Midland Ltd

Esprit House
Spon Lane
West Bromwich, B70 6AA
Tel: 0121 580 0021

Who fabricate the following timber fire doors and or doorsets

**Halspan FD30, FD60
&
Strebord FD30, FD60**

have satisfied the requirements of the SDP01 Timber Fire Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of their Factory Production Control continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 60 minutes** integrity are detailed on page 2 of this certificate.



First Issued: 25 January 2021
Revised: 28 March 2022
Valid to: 24 January 2026
Issue No: 2

A handwritten signature in black ink, appearing to read 'Ian Woodhouse'.

Ian Woodhouse
Director of Certification



175

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire. UK, HP27 9AH
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England
Page 1 of 2

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

Certificate number: IFCC 1625

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/ Test Report
Halspan 30 Prima	FD30	06166C
Halspan 60 Prima	FD60	06167C
Halspan 30 Optima	FD30	PAR/10341/01
Halspan 60 Optima	FD60	PAR/10341/02
Strebord 44	FD30	IFCA/08037, CHILT/A02066
Strebord 54	FD60	IFCA/08038, CHILT/A02067
Stredor 44	FD30	BMT/CAN/F15159
Stredor 54	FD60	WF377027

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.