



FIRE RESISTANT TIMBER FIRE DOORS

Certificate number: IFCC 1736

Certificate only valid if verified on website www.ifccertification.com

This is a product certificate to certify that

Ecosse Doors Ltd

Units 1-5, 4 MacDowall Street
Paisley, Renfrewshire
PA3 2NB Scotland
Tel:

Who fabricate the following timber fire doors and or doorsets

**Halspan FD30, FD30S, FD60, FD60S, FD90, FD90S,
FD120, FD120S**

Strebord FD30, FD30S, FD60, FD60S

Moralt FD30, FD30S, FD60, FD60S, FD90, FD90S

Flamebreak FD30, FD30S, FD60, FD60S

have satisfied the requirements of the SDP01 Timber Fire Door scheme. This includes the testing of products to **BS476: Part 22 & Part 31**, the inspection of their Factory Production Control continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes** integrity are detailed on page 2 of this certificate.



First Issued: 22 June 2022
Valid to: 21 June 2027
Issue No: 1

A handwritten signature in black ink, appearing to read 'Ian Woodhouse'.

Ian Woodhouse
Director of Certification



175

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire. UK, HP27 9AH
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

Page 1 of 2

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

Certificate number: IFCC 1736

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/ Test Report
Halspan Optima	FD30, FD30S	Chilt/A01204
Halspan Prima	FD30, FD30S	Chilt/A97174
Halspan Optima	FD60, FD60S	FEA/F01205
Halspan Prima	FD60, FD60S	FEA/F96103
Halspan Prima Panelled	FD30, FD30S	FEA/F970797
Halspan Prima Panelled	FD60, FD60S	Chilt/A01015
Halspan Prima Plus	FD60, FD60S	FEA/F96103
Halspan Prima Plus	FD90, FD90S	WF389581
Halspan Prima Plus	FD120, FD120S	WF389580
Strebord	FD30, FD30S	Chilt/A02066
Strebord	FD60, FD60S	Chilt/A02067
Strebord Panelled	FD30, FD30S	Chilt/A09104
Strebord Panelled	FD60, FD60S	Chilt/A10152
Stredor 44	FD30, FD30S	BMT/CAN/F15159
Stredor 54	FD30, FD30S	WF377027
Moralt Laminesse Firesound	FD30, FD30S	BMT/CNAF14274
Moralt Laminesse Firesound	FD30, FD30S, FD60, FD60S	WF409922
Moralt Laminesse Firesound	FD30, FD30S, FD60, FD60S FD90, FD90S	WF409923
Flamebreak	FD30, FD30S	FEA/F98164
Flamebreak	FD60, FD60S	FEA/F02141

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.