



# FIRE RESISTANT TIMBER FIRE DOORS

**Certificate number: IFCC 1674**

*Certificate only valid if verified on website - [www.ifccertification.com](http://www.ifccertification.com)*

This is a product certificate to certify that

***Msn' Fn Al-khshb***  
**Building 80, 7th Street, Zone 81**  
**New Industrial Area**  
**Doha**  
**Qatar**

Tel. +974 4451 4317

Who fabricate the following timber fire doors and or doorsets:

**Halspan FD30    Halspan FD60    Halspan FD90    Halspan FD120**  
**FireBan FD30    FireBan FD60    FireBan FD90    FireBan FD120**

have satisfied the requirements of the SDP01 Timber Fire Doors scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed in the schedules referenced below.

Schedule refs: HS01 - HS06, GTLS03 – GTLS04



First Issued: 04 November 2021  
Valid to: 03 November 2026  
Issue No: 1



175

Ian Woodhouse  
Director of Certification

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire. HP27 9AH, UK  
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: [info@ifccertification.com](mailto:info@ifccertification.com) Web: [www.ifccertification.com](http://www.ifccertification.com)  
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.