



FIRE RESISTANT TIMBER FIRE DOORS

Certificate number: IFCC 1588

Certificate only valid if verified on website - www.ifccertification.com

This is a product certificate to certify that

Newline Joinery Ltd.,

21 Bennett Place
Dartford
Kent
DA1 5FR
Tel: 07428886680

Who fabricate the following timber fire doors and or doorsets

**Halspan FD30, FD30S, FD60, FD60S
FD90, FD120, Strebord FD30, FD30S,
FD60, FD60S & Egger FD30**

have satisfied the requirements of the SDP01 Timber Fire Doors scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed in the schedules on page 2 of the certificate.



First Issued: 08 September 2020

Revised: 14 December 2021

Valid to: 07 September 2025

Issue No: 3

Ian Woodhouse
Director of Certification



175

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire. HP27 9AH, UK
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

Page 1 of 2

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

Certificate number: IFCC 1588

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/ Test Report
Halspan Optima	FD30	HS03 PAR/10341/01
Halspan Optima	FD60	HS04 PAR/10341/02
Halspan Prima	FD30	HS01 06166
Halspan Prima	FD60	HS02 06167
Halspan	FD90	HS05 PAR/10513/01
Halspan	FD120	HS06 PAR/10513/02
Egger	FD30	Chilt/A10385
Strebord 44	FD30	Chilt/A02066
Strebord 54	FD60	Chilt/A02067

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.