

## FIRE RESISTANT TIMBER DOOR SCHEME

***Certificate number: IFCC 1363***

This is a product certificate to certify that

### ***WKS Door Systems SA DE CV***

Textil #101, Parque Industrial Escobedo,  
Escobedo N.L. Mexico

Tel: +52 (0181) 81548700

who fabricate the following timber fire doors:

### **Own Design FD30 & FD60**

have satisfied the requirements of the SDP01 Fire resistant Timber Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 60 minutes integrity** are detailed on page 2 of this certificate.



Initial certification: 16 May 2018  
Revised: 19 October 2021  
Valid to: 15 May 2023  
Issue status: 4



175



Ian Woodhouse  
Director of Certification

---

IFC Certification Ltd  
20 Park Street, Princes Risborough, Buckinghamshire. England HP27 9AH  
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: [info@ifccertification.com](mailto:info@ifccertification.com) Web: [www.ifccertification.com](http://www.ifccertification.com)  
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

F27 ©IFC Certification Ltd 2004



***Certificate number: IFCC 1393***

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

| <b>Doorset Description</b>  | <b>Fire Rating</b> | <b>Assessment/ Test Report</b> |
|---|--------------------|--------------------------------|
| Solid Core & Sandwich Core Door Leaves installed in Timber Frames | FD30               | PAR/13211/02                   |
| Solid Core Door Leaves installed in Timber Frames                 | FD60               | PAR/13211/03                   |

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

**It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.**

**Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.**

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

F27 ©IFC Certification Ltd 2004