



FIRE RESISTANT TIMBER DOOR SCHEME

Certificate number: IFCC 1364

This is a product certificate to certify that

UK Doorsets Ltd

Unit 10, Spartan Ind Centre
Brickhouse Lane
Great Bridge, West Bromwich
West Midlands B70 0DH
Tel: 0121 521 2175

who fabricate the following timber fire doors & fire resistance timber based doorsets:

**Halspan FD30, FD60, Flamebreak FD30, FD60,
Blankfort FD30, FD60, Strebord FD30, FD60,
Stredor FD30, FD60, Safehinge FD30, FD60,
Fibrecore FD60, Duocore FD30,
Tri-Sound FD30, FD60, Warmsprings FD60, FD90, FD120
Moralt FD30, FD60, Vicaima FD30, FD60, Deanta FD30
Construction Specialities FD30, FD60**

have satisfied the requirements of the SDP01 Fire Resistant Timber Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed on page 2 of this certificate.



Initial certification: 22 March 2018

Revised: 16 March 2022

Valid to: 21 March 2023

Issue status: 4

Ian Woodhouse
Director of Certification



175

Page 1 of 3

IFC Certification Ltd
20 Park Street, Princes Risborough, Buckinghamshire. England HP27 9AH
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

Certificate number: IFCC 1364

The production of fire resistance timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/Test Report
Halspan Prima	FD30	IFCA/06166
Halspan Prima	FD60	IFCA/06167
Halspan Optima	FD30	Chilt/A01204 PAR/10341/01
Halspan Optima	FD60	FEA/F01205 PAR/10341/02
Halspan – Prima 30 & Prima Plus 30	FD30	FEA/F97174 PAR/15953/01
Halspan – Prima 60 & Prima Plus 60	FD60	FEA/F96103 IFCA/15953/02
Flamebreak 30	FD30	FEA98164
Flamebreak 60	FD60	FEA/F02141
Blankfort 30/30+	FD30	Chilt/A12151
Blankfort 60/60+	FD60	Chilt/A12152
STREBORD	FD30	Chilt/A02066, IFCA/08037
STREBORD	FD60	Chilt/A02067, IFCA/08038
STREDOR	FD30	BMT/CNA/F15159
STREDOR	FD30 & FD60	WF377027
Safehinge	FD30 & FD60	Chilt/A12005
Fibrecore	FD60	PAR/14658/01
Duocore	FD30	Chilt/A12296
Trisound	FD30	PAR/12033/01
Trisound	FD60	PAR/13088/01
Warmsprings	FD60, FD90, FD120	IFCA/07019
Moralt Laminesse FireSmoke & FireSafe	FD30	PAR/12519/01
Moralt Laminesse FireSmoke	FD60	PAR/12519/02
Moralt Laminesse FireSound	FD30	PAR/14559/01
Moralt Laminesse FireSound	FD30 & FD60	PAR/12519/03
Vicaima	FD30	FEA/F99112
Vicaima	FD60	Chilt/A13093
Deanta Type 1 & 2	FD30	WF399982
Deanta Type 3	FD30	WF399990
Deanta Type 4	FD30	WF399991
Deanta Type 5	FD30	WF399992
Construction Specialities – Door edge protectors	FD30	Chilt/A11129
Construction Specialities – Door edge protectors	FD60	Chilt/A11130

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificates holder's responsibility to ensure that the latest version/revision of the above assessment/test reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.