



FIRE RESISTANT TIMBER DOOR SCHEME

Certificate number: IFCC 1413

This is a product certificate to certify that

Butler Doors Ltd

Unit 28 Coast Business Park,
1 Wesley Way, Benton,
Newcastle upon Tyne
NE12 9TA
Tel: 0191 4282304

who fabricate the following timber fire doors:

Halspan FD30, FD60 Vicaima FD30, FD60 Flamebreak FD30, FD60

have satisfied the requirements of the SDP01 Fire resistant Timber Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 60 minutes integrity** are detailed on page 2 of this certificate.



Initial certification: 14 Sept 2018
Revised: 21 April 2021
Valid to: 13 Sept 2023
Issue status: 2



175

Ian Woodhouse
Director of Certification

IFC Certification Ltd
20 Park Street, Princes Risborough, Buckinghamshire. England HP27 9AH
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

F27 ©IFC Certification Ltd 2004

Certificate number: IFCC 1413

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/ Test Report
Halspan Optima	FD30	Chilt/A01204
Halspan Optima	FD60	Chilt/A01205
Halspan Prima	FD30	FEA/F97174
Halspan Prima	FD60	FEA/F96103
Vicaima	FD30	FEA/F99112A
Vicaima	FD60	Chilt/A03190
Sealed Tight Solutions	FD30	PAR 16520/01
Sealed Tight Solutions	FD60	PAR 16521/01
Flamebreak	FD30	FEA/F98164
Flamebreak	FD60	FEA/F02141
Intastop	FD30, FD60	PAR/11800/01

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.