



FIRE RESISTANT TIMBER DOOR SCHEME

Certificate number: IFCC 1511

Certificate only valid if verified on website - www.ifccertification.com

This is a product certificate to certify that

XL Joinery Limited

Holden Ing Way, Birstall,
Batley,
WF17 9AD

Tel: 01924 350501

Who fabricate the following timber fire doors and or doorsets:

Own Design FD30 & FD30S
Own Design FD60 & FD60S

have satisfied the requirements of the SDP01 Fire resistant Timber Door scheme. This includes the testing of products to **BS476: Part 22 & BS476: Part 31**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve up to **60 minutes integrity** are detailed on page 2 of this certificate.

Manufacturing sites: GG01, HH01



Initial certification: 18 March 2020
Revised: 07 December 2021
Valid to: 17 March 2025
Issue status: 3



175

Ian Woodhouse
Director of Certification

IFC Certification Ltd
20 Park Street, Princes Risborough, Buckinghamshire. England HP27 9AH
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

F27 ©IFC Certification Ltd 2004

Certificate number: IFCC 1511

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/ Test Report
Flush & Panelled	FD30	BMT/CAN/F14268
Panelled	FD30	WF 387293
Glazed	FD30	WF 369769
Unglazed	FD60	WF 381911

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder’s responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.