



FIRE RESISTANT TIMBER DOOR SCHEME

Certificate number: IFCC 1559

**Certificate only valid if verified on website -
www.ifccertification.com**

This is a product certificate to certify that

E E Smith Contracts Ltd

25 Morris Road,
Leicester
LE2 6AL

Tel: 0116 2706946

Who fabricate the following timber fire doors and or doorsets:

**Halspan FD30, FD60, FD90, FD120 Protech FD30,
FD60, Moralt FD30, FD60, Blankfort FD30, FD60,
Flamebreak FD30, FD60, Strebord FD30, FD60,
Stredor FD30, FD60, Fibrecore FD30,
Duocore FD30, Tri-Sound FD30, FD60,
Own Design FD30, FD60**

have satisfied the requirements of the SDP01 Fire resistant Timber Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed on page 2 of this certificate.



Initial certification: 13 July 2020

Revised: 01 November 2022

Valid to: 12 July 2025

Issue status: 5

Ian Woodhouse
Director of Certification



175

IFC Certification Ltd

20 Park Street, Princes Risborough, Buckinghamshire. England HP27 9AH

Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com

Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

F27 ©IFC Certification Ltd 2004

Certificate number: IFCC 1559

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/ Test Report
Halspan Prima	FD30	HS01 IFCA 06166
Halspan Prima	FD60	HS02 IFCA 06167
Prima Panelled	FD60	Chilt/A01015
Halspan Optima	FD30	HS03 PAR/10341/01
Halspan Optima	FD60	HS04 PAR/10341/02
Halspan 90	FD90	HS05 PAR/10513/01
Halspan 120	FD120	HS06 PAR/10513/02
Prima Plus	FD30	PAR/15953/01
Prima Plus	FD60	IFCA/15953/02
Prima Plus	FD90	PAR/17519-01
Prima Plus	FD120	PAR/17519-02
Protech	FD30	Chilt/A13242
Protech	FD60	Chilt/A13227
Moralt Laminesse FireSmoke & FireSafe	FD30	PAR/12519/01
Moralt Laminesse FireSmoke & FireSafe	FD60	PAR/12519/02
Moralt Laminesse FireSound	FD30 & FD60	PAR/14559/01
Moralt Laminesse FireSound 54, Plus 54 & 59	FD30 & FD60	PAR/21569/01
Blankfort 30/30+	FD30	Chilt/A12151
Blankfort 60/60+	FD60	Chilt/A12152
Flamebreak 30	FD30	FEA/F98164
Flamebreak 60	FD60	Chilt/A02141
STREBORD	FD30	Chilt/A02066, IFCA/08037
STREBORD	FD60	Chilt/A02067, IFCA/08038
STREDOR	FD30	CNA/F15159
STREDOR	FD60	WF377027
Duocore	FD30	Chilt/A12296
Trisound	FD30	PAR/12033/01
Trisound	FD60	PAR/13088/01
Own Design	FD30	PAR/19174/01
Own Design	FD30, FD60	PAR/19174/02
Own Design	FD30, FD60	PAR/19174/03
Own Design	FD30, FD60	PAR/19174/04
Own Design	FD30, FD60	PAR/20285/01
Own Design	FD30	PAR/20285/02

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.