



FIRE RESISTANT TIMBER FIRE DOORS

Certificate number: IFCC 1046

This is a product certificate to certify that

Riyan Overseas LLC

PO Box 884

P.Code 117, Wadi Kabir, Muscat

Sultanate of Oman

Telephone No. +968 2 481 8355 Fax No. +968 2 481 8142

Email: firedoors@riyanmuscat.com, mail@riyanmuscat.com

Who fabricate the following fire doors:

Strebord FD30, FD60 Ramkor FD 90

Kingsa FD30, FD60, FD90, FD120

Halspan FD30, FD60, FD90, FD120

FireBan FD30, FD60, FD90, FD120

have satisfied the requirements of the SDP01 Timber Fire Doors scheme. This includes the testing of products to **BS476: Part 22**, the inspection of their Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30, 60, 90 and 120 minutes integrity** are detailed in the schedule referenced below.



Schedules ref: SS01, SS02, RA01,
KS01, KS02, KS03, HS01-HS06

First Issued: 17 October 2013

Re-issued: 17 October 2018

Revised 29 November 2018

Valid to: 16 October 2023

Issue No: 5



175

Ian Woodhouse
Director of Certification

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire. UK, HP27 9AH
Tel: +44 (0)1844 275500 Fax: +44 (0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.