



FIRE RESISTANT TIMBER DOOR SCHEME

Certificate number: IFCC 1414

This is a product certificate to certify that

Woodmarque Architectural Joinery

16 Mullaghbane Rd.,
Dungannon, Co. Tyrone
BT70 1SR
UK
Tel: 02887724907

who fabricate the following timber fire doors:

Halspan FD30, FD60, FD90 & FD120
Strebord FD30, FD60, FD90 & FD120
Egger FD30 & FD60
Moralt FD30 & FD60, Vicaima FD30 & FD60

have satisfied the requirements of the SDP01 Fire Resistant Timber Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed on page 2 of this certificate.



Initial certification: 10 October 2018
Valid to: 08 October 2023
Issue status: 1

Ian Woodhouse
Director of Certification



175

IFC Certification Ltd
20 Park Street, Princes Risborough, Buckinghamshire. England HP27 9AH
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

F27 ©IFC Certification Ltd 2004

Certificate number: IFCC 1414

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/ Test Report
Halspan Optima	FD30	Chilt/A01204
Halspan Optima	FD60	Chilt/A01205
Halspan Prima	FD30	FEA/F97174
Halspan Prima	FD60	FEA/F96103
Halspan	FD90	Chilt/A05151
Halspan	FD120	BMT/CAN/F15082
Strebord 44	FD30	Chilt/A02066
Strebord 54	FD60	Chilt/A02067
Stredor 44	FD30	BMT/CAN/F15159
Stredor 54	FD60	WF377027
WSCP	FD60, FD90 & FD120	Chilt/A12138
Egger Eurospan	FD30	Chilt/A13085
Egger Eurospan	FD60	Chilt/A10187
Moralt Laminesse Klassik & FireSmoke	FD30	PAR/14247/01
Moralt Laminesse FireSmoke & FireSafe	FD30	PAR/12519/01
Moralt Laminesse FireSmoke & FireSafe	FD60	PAR/12519/02
Moralt Laminesse FireSound	FD30 & FD60	PAR/14559/01
Moralt Laminesse FireSound	FD30 & FD60	PAR/12519/03
Vicaima	FD30	FEA/F99112A
Vicaima	FD60	Chilt/A03190

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.