



FIRE RESISTANT TIMBER FIRE DOORS

Certificate number: IFCC 1223

This is a product certificate to certify that

J & P Carpentry & Joinery Limited

7 Advanced Business Park
Burdock Close, Cannock
Staffordshire WS11 7FG
Tel: 01543 506699

Who fabricate the following fire doors:

Strebord FD30 Strebord FD60 Stredor44 FD30 Stredor54 FD60
Vicaima FD30 Vicaima FD60 Tri-Sound FD30* Tri-Sound FD60*
Warmsprings FD60 Warmsprings FD90 Warmsprings FD120
Halspan FD30 Halspan FD60 Halspan FD90 Halspan FD120
Halspan Prima Plus FD30/FD60

have satisfied the requirements of the scheme SDP01. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from 30 minutes to 120 minutes integrity are detailed on page 2 of this certificate.

*Note: Certification relates only to the Fire Performance of these doors, no acoustic performance is certificated.



First Issued: 31 March 2016
Revised: 06 December 2018
Valid to: 30 March 2021
Issue No: 4



175

Ian Woodhouse
Director of Certification

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire. UK, HP27 9AH
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

Certificate number: IFCC 1223

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Description	Fire Rating	Assessment/ Test Report
Strebord	FD30	IFCA/08037
Strebord	FD60	IFCA/08038
Stredor 44	FD30	BMT/CAN/F15159
Stredor 54	FD60	WF 377027
Warmssprings	FD60, FD90, FD120	IFCA/07019
Trisound	FD30	PAR/12033/01
Trisound	FD60	PAR/13088/01
Vicaima	FD30	FEA/F99112A
Vicaima	FD60	Chilt/A13093
Halspan Prima	FD30	06166 (HS01)
Halspan Prima	FD60	06167 (HS02)
Halspan Optima	FD30	PAR/10341/01 (HS03)
Halspan Optima	FD60	PAR/10341/02 (HS04)
Halspan	FD90	PAR/10513/01 (HS05)
Halspan	FD120	PAR/10513/02 (HS06)
Halspan Prima Plus	FD30	IFCA/15953/01
Halspan Prima Plus	FD60	IFCA/15953/02

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.