



# FIRE RESISTANT TIMBER FIRE DOORS

***Certificate number: IFCC 1003***

This is a product certificate to certify that

## ***Decorelle***

6<sup>th</sup> Floor, Al Jassim Commercial Tower  
C Ring Road  
Suhaim Bin Hamad Street  
P.O. Box 21557, Doha  
Qatar  
Telephone no. +974 4427 6049

Who fabricate the following fire doors:

**Halspan FD30   Halspan FD60   Halspan FD90   Halspan FD120**  
**Kingsa FD30   Kingsa FD60   Kingsa FD90   Kingsa FD120**  
**Strebord FD30   Strebord FD60**

have satisfied the requirements of the SDP01 Timber Fire Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed in the schedules referenced below.

Schedule ref: HS01, HS02, HS03, HS04, HS05, HS06, KS01,  
KS02, KS03, KS04 SS01, SS02, SS03



First Issued: 28 February 2013  
Reissued 21 March 2018  
Valid to: 27 February 2023  
Issue No: 4

Ian Woodhouse  
Director of Certification



175

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire, HP27 9AH, UK  
Tel: +44 (0)1844 275500 Fax: +44 (0)1844 274002 E-mail: [info@ifccertification.com](mailto:info@ifccertification.com) Web: [www.ifccertification.com](http://www.ifccertification.com)  
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.