



FIRE RESISTANT TIMBER FIRE DOORS

Certificate number: IFCC1325

This is a product certificate to certify that

Apton Partioning Limited

Unit 3, Cannon Business Park,
Gough Road, Coseley,
West Midlands,
WV14 8XR

Tel: 01902 385250

Who fabricate timber fire doors:

**Vicaima FD30 Vicaima FD60
Strebord FD30 Strebord FD60**

have satisfied the requirements of the above scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The frame specification and field of application for the doors to achieve from **30 minutes to 60 minutes integrity** are detailed on page 2 of this certificate.

Fire doors manufactured at factory reference: A-AB9



First Issued: 04 April 2018
Revised: 14 April 2018
Valid to: 03 April 2023
Issue No: 2

A handwritten signature in black ink, appearing to read 'Ian Woodhouse', is written over a light-colored background.

Ian Woodhouse
Director of Certification



175

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire. Tel: +44 (0)1844 275500 Fax: +44 (0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.



Certificate number: IFCC 1325

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/ Test Report
Vicaima	FD30	FEA/F99112A Rev. I
Vicaima	FD60	Chit/A13093
Strebord 44	FD30	IFCA/08037 Rev C
Strebord 54	FD60	IFCA/08038 Rev B

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.