



# FIRE RESISTANT TIMBER FIRE DOORS

***Certificate number: FRTD533***

*Certificate only valid if verified on website - [www.ifccertification.com](http://www.ifccertification.com)*

This is a product certificate to certify that

***Jordan Wood Industries Co. Ltd***

Po Box 5272

Amman 11183

Jordan

Telephone no. +9626 420 1171

Who fabricate the following timber fire doors and or doorsets:

**Halspan FD30 Halspan FD60 Halspan FD90 Halspan FD120**

**Strebord FD30 Strebord FD60**

**Warm Springs FD90 Warm Springs FD120**

**FireBan FD30 FireBan FD60 FireBan FD90**

have satisfied the requirements of the SDP01 Timber Fire Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed in the schedules referenced below.

Schedule ref: HS01, HS02, HS03, HS04, HS05, HS06, SS01, SS02, WS02, GTLS03



First Issued: 17 March 2011

Reissued: 13 April 2021

Valid to: 16 March 2026

Issue No: 6

Ian Woodhouse

Director of Certification



175

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire. UK, HP27 9AH  
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: [info@ifccertification.com](mailto:info@ifccertification.com) Web: [www.ifccertification.com](http://www.ifccertification.com)  
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.