



FIRE RESISTANT TIMBER DOOR SCHEME

Certificate number: IFCC 1598

Certificate only valid if verified on website - www.ifccertification.com

This is a product certificate to certify that

J D Doors Ltd

Unit 6a, Road Four
Winsford Industrial Estate
Winsford, Cheshire
CW7 3RS
Tel: 01606 550529

Who fabricate the following timber fire doors and or doorsets:

**Strebord FD30, FD60 Flamebreak FD30, FD60
Halspan FD30, FD60, FD90, FD120**

have satisfied the requirements of the SDP01 Fire Resistant Timber Door scheme. This includes the testing of products to **BS476: Part 22** the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed on page 2 of this certificate.



Initial certification: 30 September 2020

Revised: 04 October 2021

Valid to: 29 September 2025

Issue status: 2



175

Ian Woodhouse
Director of Certification

Page 1 of 2

IFC Certification Ltd

20 Park Street, Princes Risborough, Buckinghamshire. England HP27 9AH

Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com

Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

Certificate number: IFCC 1598

The production of fire resistance timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/Test Report
Strebord	FD30	IFCA/08037
Strebord	FD60	IFCA/08038
Flamebreak	FD30	FEA/F98164
Flamebreak	FD60	FEA/F02141
Halspan 30 Prima	FD30	HS01 06166
Halspan 60 Prima	FD60	HS02 06167
Halspan 30 Optima	FD30	HS03 PAR/10341/01
Halspan 60 Optima	FD60	HS04 PAR/10341/02
Halspan 90	FD90	HS05 PAR/10513/01
Halspan 120	FD120	HS06 PAR/10513/02

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/revision of the above assessment/test reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.