



## FIRE RESISTANT TIMBER DOOR SCHEME

**Certificate number: IFCC 1689**

*Certificate only valid if verified on website - [www.ifccertification.com](http://www.ifccertification.com)*

This is a product certificate to certify that

***XL Joinery Limited***

Holden Ing Way, Birstall,  
Batley,  
WF17 9AD

Tel: 01924 350501

Who fabricate the following timber fire doors and or doorsets:

**Own Design EI30 & EI30Sa**  
**Own Design EI60 & EI60Sa**

have satisfied the requirements of the SDP01 Fire Resistant Timber Door scheme. This includes the testing of products to EN1634-1 the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from 30 minutes to 60 minutes integrity & insulation are detailed on page 2 of this certificate.

Manufacturing sites: GG01, HH01



Initial certification: 09 December 2021

Revised: 02 March 2022

Valid to: 08 December 2026

Issue status: 2

Ian Woodhouse  
Director of Certification



175

IFC Certification Ltd

20 Park Street, Princes Risborough, Buckinghamshire. England HP27 9AH

Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: [info@ifccertification.com](mailto:info@ifccertification.com) Web: [www.ifccertification.com](http://www.ifccertification.com)

Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

F27 ©IFC Certification Ltd 2004

***Certificate number: IFCC 1689***

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

<b>Doorset Description</b>	<b>Fire Rating</b>	<b>Assessment/ Test Report</b>
Suffolk Oak	EI30, EI30Sa	20/22153-571-1
Suffolk Oak	EI60, EI60Sa	20/22153-572-1
Palermo	EI30, EI30Sa	20/22153-1376-1 M1
Palermo	EI60, EI60Sa	21/24155-1534

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

**It is the certificate holder’s responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.**

**Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.**

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.