



FIRE RESISTANT TIMBER FIRE DOORS

Certificate number: IFCC1655

Certificate only valid if verified on website www.ifccertification.com

This is a product certificate to certify that

H&S Joinery Ltd

Thwaites Close
Shadsworth Business Park
Blackburn BB1 2QQ

Tel: 01254 696 931

Who fabricate the following timber fire doors and or doorsets

Timber Panelled Doorsets FD30, FD60, FD30S, FD60S
Flamebreak FD30, FD60, FD30S, FD60S
Strebord/Stredor FD30, FD60, FD30S, FD60S,
Halspan FD30, FD60, FD30S, FD60S,
Moralt FD30, FD60, FD30S, FD60S
Blankfort FD30, FD60, FD30S, FD60S

have satisfied the requirements of the SDP01 Timber Fire Door scheme. This includes the testing of products to **BS476: Part 22 & Part 31**, the inspection of their Factory Production Control continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 60 minutes** integrity are detailed on page 2 of this certificate.



First Issued: 09 November 2021

Revised: 14 November 2022

Valid to: 08 November 2026

Issue No: 3

Ian Woodhouse
Director of Certification



175

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire. UK, HP27 9AH
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

Page 1 of 2

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

Certificate number: IFCC 1655

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/ Test Report
Timber Panelled Doorsets	FD30, FD30S	Chilt/A09136
Timber Panelled Doorsets	FD60, FD60S	Chilt/A09165
Flamebreak	FD30, FD30S	FEA/F98164
Flamebreak	FD60, FD60S	FEA/F02141
Strebord	FD30, FD30S	IFCA/08037
Strebord	FD60, FD60S	Chilt/A02067
Stredor 44	FD30, FD30S	BMT/CAN/F15159
Stredor 54	FD30, FD30S	WF377027
Moralt	FD30, FD30S	Chilt/A13058
Moralt	FD60, FD60S	Chilt/A13059
Halspan Optima	FD30, FD30S	PAR/10341/01
Halspan Prima	FD30, FD30S	IFCA/06166
Halspan Optima	FD60, FD60S	FEA/F01205
Halspan Prima	FD60, FD60S	FEA/F96103
Blankfort 30 & 30 Plus	FD30, FD30S	Chilt A12151
Blankfort 60 & 60 Plus	FD60, FD60S	Chilt A12152

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.