



# FIRE RESISTANT TIMBER FIRE DOORS

**Certificate number: IFCC 1762**

*Certificate only valid if verified on website - [www.ifccertification.com](http://www.ifccertification.com)*

This is a product certificate to certify that

***Basic Workshop***  
**Building No 71, Zone 57, Street 18**  
**Doha**  
**Qatar**

Tel. 00974-40059991

Who fabricate the following timber fire doors and or doorsets:

<b>Halspan FD30</b>	<b>Halspan FD60</b>	<b>Halspan FD90</b>	<b>Halspan FD120</b>
<b>FireBan FD30</b>	<b>FireBan FD60</b>	<b>FireBan FD90</b>	<b>FireBan FD120</b>

have satisfied the requirements of the SDP01 Timber Fire Doors scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed in the schedules referenced below.

Schedule refs: HS01 - HS06, GTLS03, GTLS04



First Issued: 03 November 2022

Valid to: 02 November 2027

Issue No: 1

Ian Woodhouse  
Director of Certification



175

IFC Certification Ltd, Ground Floor, Suite A, Building 2, Bear Brook Office Park, Walton St, Aylesbury, HP21 7GQ, UK  
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: [info@ifccertification.com](mailto:info@ifccertification.com) Web: [www.ifccertification.com](http://www.ifccertification.com)  
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.