



FIRE RESISTANT TIMBER FIRE DOORS

Certificate number: FRTD 410

This is a product certificate to certify that

Halspan Limited

Regent House, Regent Centre
Linlithgow
West Lothian EH49 7HU

Tel: +44 (0) 1506 827538 Fax: +44 (0) 1506 825996
E-mail: doors@halspan.com Web: www.halspan.com

Who supply door blanks for the manufacture of the following fire doors & doorsets:

Manufacturing sites: F-C, KK, A-ZH

Halspan Optima FD30	Halspan Optima FD60
Halspan Prima FD30	Halspan Prima FD60
Halspan Panelled Prima/Optima FD30	Halspan Panelled Prima FD60
Halspan FD90	Halspan FD120
Halspan Prima Plus FD30	Halspan Prima Plus FD60
Halspan Prima Plus FD90	Halspan Prima Plus FD120
Halspan Prima Plus Enhanced FD60	
Halspan XT30	Halspan IT30
Halspan XT60	Halspan IT60

have satisfied the requirements of the scheme SDP01. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from 30 minutes to 120 minutes integrity are detailed on page 2 of this certificate.



First Issued: 1 February 2006
Reissued: 27 January 2022
Revised: 11 April 2022
Valid to: 31 January 2027
Issue No: 17



175

Ian Woodhouse
Director of Certification

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire. UK, HP27 9AH
Tel: +44 (0)1844 275500 Fax: +44(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Description	Fire Rating	Assessment/ Test Report
Halspan Prima	FD30	06166B (HS01)
Halspan Prima	FD60	06167C (HS02)
Halspan Optima	FD30	PAR/10341/01 (HS03)
Halspan Optima	FD60	PAR/10341/02 (HS04)
Halspan Panelled Prima/Optima	FD30	FEA F97097
Halspan Panelled Prima	FD60	A01015
Halspan	FD90	PAR/10513/01 (HS05)
Halspan	FD120	PAR/10513/02 (HS06)
Halspan Prima Plus	FD30	IFCA/15953/01 (HS10)
Halspan Prima Plus	FD60	IFCA/15953/02 (HS11)
Halspan Prima Plus	FD90	PAR/17519/01 (HS12)
Halspan Prima Plus	FD120	PAR/17519/02 (HS13)
Halspan Prima Plus Enhanced	FD60	PAR/16286/01 (HS14)
Halspan XT30	FD30	PAR/20910/01 (HS08)
Halspan IT30	FD30	PAR/20910/01 (HS08)
Halspan XT60	FD60	PAR/21548/01 (HS09)
Halspan IT60	FD60	PAR/21548/01 (HS09)

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.