



## **FIRE RESISTANT TIMBER FIRE DOORS**

***Certificate number: FRTD519***

*Certificate only valid if verified on website [www.ifccertification.com](http://www.ifccertification.com)*

This is a product certificate to certify that

### ***ID Project SAL***

3<sup>rd</sup> FLOOR I.C.F. Building  
Mkales Main Road  
Beirut, Lebanon

Tel: + (961) 1 694 678 Fax: +(961) 1 694 698  
E-mail: info@idproject-lb.com Web: www.idplebanon.com

Who fabricate the following timber fire doors and or doorsets:

**Halspan FD30      Halspan FD90**  
**Halspan FD60      Halspan FD120**

have satisfied the requirements of the SDP01 Timber Fire Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed in the schedules referenced below.

Schedule ref: HS01, HS02, HS03, HS04, HS05, HS06



First Issued: 1<sup>st</sup> October 2010  
Re-issued: 5<sup>th</sup> August 2021  
Valid to: 30<sup>th</sup> September 2026  
Issue No: 4



175

A handwritten signature in black ink, appearing to read 'Ian Woodhouse'.

**Ian Woodhouse**  
Director of Certification

---

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire. UK, HP27 9AH  
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: [info@ifccertification.com](mailto:info@ifccertification.com) Web: [www.ifccertification.com](http://www.ifccertification.com)  
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.