



FIRE RESISTANT TIMBER FIRE DOORS

Certificate number: IFCC 1039

This is a product certificate to certify that

Elegancia Joinery WLL

PO Box 24059

Doha - Qatar

Telephone no.+974 4434 0704

Who fabricate the following fire doors:

Halspan FD30 Halspan FD60 Halspan FD90 Halspan FD120
FireBan FD30 FireBan FD60 FireBan FD90 FireBan FD120
Strebord 44 FD30 Strebord 54 FD60
Warmsprings FD60 Warmsprings FD90 Warmsprings FD120
Own Design SASL & SADL Fireban FD120 with marble cladding

have satisfied the requirements of the above scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed in the schedules referenced below.

Schedule ref: HS01, HS02, HS03, HS04, HS05, HS06, GTLS03, GTLS04 SS01, SS02, WS02
Test Reports: TBW VF32-1B, TBW VF32-2B, TBW VF32-3B, TBW VF32-4B



First Issued: 19 September 2013
Revised: 13 October 2022
Re-issued: 7 September 2018
Valid to: 18 September 2023
Issue No: 7



175

Ian Woodhouse
Director of Certification

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire. UK, HP27 9AH
Tel: +44 (0)1844 275500 Fax: +44 (0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.