



FIRE RESISTANT TIMBER FIRE DOORS

Certificate number: IFCC 1682

Certificate only valid if verified on website - www.ifccertification.com

This is a product certificate to certify that

Compania Madeira Systems SA

2nd Km Sindos-Chalastra

Thessaloniki

Sindos

57400

Greece

Tel. +30 2310795080

Who fabricate the following timber fire doors and or doorsets:

**Halspan
FD30/FD30S**

**Halspan
FD60/FD60S**

**Halspan
FD90/FD90S**

**Halspan FD120/
FD120S**

**Strebord
FD30/FD30S**

**Strebord
FD60/FD60S**

have satisfied the requirements of the SDP01 Timber Fire Doors scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed in the schedules referenced below.

Schedule refs: HS01 - HS06, SS01, SS02



First Issued: 13 December 2021

Valid to: 12 December 2026

Issue No: 1

Ian Woodhouse
Director of Certification



175

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire. HP27 9AH, UK
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.