



FIRE RESISTANT TIMBER FIRE DOORS

Certificate number: IFCC1582

Certificate only valid if verified on website www.ifccertification.com

This is a product certificate to certify that

Elite Door Solutions Ltd (Luxury Door Solutions)

Unit 2 Carlton Dept
Carlton Industrial Estate
Industry Road, Barnsley
S71 3PQ
UK

Tel: 07394563187

Who fabricate the following timber fire doors and or doorsets

**Timber Panelled Doorsets FD30,FD30S,FD60,FD60S,
Halspan FD30,FD60,FD120
Strebord FD30,FD60,
Flamebreak FD30,FD60 & Vicaima FD30,FD60**

have satisfied the requirements of the SDP01 Timber Fire Door scheme. This includes the testing of products to **BS476: Part 22 & Part 31**, the inspection of their Factory Production Control continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 60 minutes** integrity are detailed on page 2 of this certificate.



First Issued: 10 August 2020
Revised 03 May 2022
Valid to: 09 August 2025
Issue No: 3

Ian Woodhouse
Director of Certification



175

IFC Certification Ltd, 20 Park Street, Princes Risborough, Buckinghamshire. UK, HP27 9AH
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England
Page 1 of 2

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

Certificate number: IFCC 1582

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/ Test Report
Timber Panelled Doorsets	FD30, FD30S	Chilt/A09136
Timber Panelled Doorsets	FD60, FD30S	Chilt/A09165
Stredor	FD30	BMT/CNA/F15159
Stredor	FD60	WF377027
Strebord 44	FD30	Chilt/A02066
Strebord 54	FD60	Chilt/A02067
Halspan Optima	FD30	Chilt/A01204
Halspan Optima	FD60	Chilt/A01205
Halspan Prima/Prima Plus	FD30	FEA/F97174
Halspan Prima/Prima Plus	FD60	FEA/F96103
Halspan Prima/Prima Plus	FD120	BMT/CNA/F15082
Flamebreak	FD30	FEA/F98164
Flamebreak	FD60	FEA/F02141
Vicaima	FD30	FEA/F99112A
Vicaima	FD60	Chilt/A13093

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.